03500.016230 PATENT

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:)	
	:	Examiner: L. Liang
SADATOSHI NARAZAKI, ET AL.)	
	:	Group Art Unit: 2853
Appln. No.: 10/082,182)	
	:	Patent No.: US 6,926,380 B2
Filed: February 26, 2002)	
	:	Issued: August 9, 2005
For: INK JET RECORDING APPARATUS)	
PROVIDED WITH INTERRUPT CONTROL	:	Confirmation No.: 2431
CIRCUIT AND METHOD FOR)	
CONTROLLING RECORDING APPARATUS	:	October 5, 2006

Commissioner for Patents P.O. Box 1450

Alexandria, VA 22313-1450

Attention: CERTIFICATE OF CORRECTION BRANCH

REQUEST FOR CERTIFICATE OF CORRECTION UNDER RULES 322 AND 323

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form (Form PTO-1050), in duplicate, is enclosed.

The statutory fee of \$100.00 is being paid electronically. Any additional fee required by this paper may be charged to Deposit Account No. 06-1205.

Patentees' undersigned attorney may be reached by telephone in our Washington, D.C. office at (202) 530-1010 or by facsimile at (202) 530-1055. All correspondence should be directed to our address given below.

Respectfully submitted,

/Mark A. Williamson/

Mark A. Williamson Attorney for Patentees Registration No. 33,628

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3800 Facsimile: (212) 218-2200

MAW/llp

DC MAIN 218902v1

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : US 6,926,380 B2

DATED: August 9, 2005

INVENTOR(S) : Narazaki et al. Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 1

Line 39, "referred to" should read --referred to as--.

COLUMN 2

Line 9, "from," should read --from--.

COLUMN 7

Line 56, "des ignates" should read --designates --.

COLUMN 11

Line 64, "is" should be deleted.

Line 65, "step S1." should read --step S11.--.

COLUMN 12

Line 28, "lever" should read --level--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3800

(212) 218-2100 - Telephone (212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82)

(Form#30) MAW/Ib DC MAIN 218907

PATENT NO. US 6,926,380 B2

No. of add'l. copies @ 30¢ per page



UNITED STATES PATENT AND TRADEMARK OFFICE. CERTIFICATE OF CORRECTION

PATENT NO. : US 6,926,380 B2

DATED : August 9, 2005

INVENTOR(S) : Narazaki et al. Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 19

Line 45, "on/off" should read --ON/OFF--.

Line 48, "stop mode or halt" should read --STOP mode or HALT--.

Line 49, "on/off" should read -- ON/OFF--.

Line 51, "stop" should read --STOP--, and "half" should read --HALT--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3800 (212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82) (Form#30) MAW/In DC MAIN 218907 PATENT NO. US 6,926,380 B2

No. of add'l. copies @ 30¢ per page

